



## Reagents, Catalyst, Oxidation, and Supplies

Elementar#	Sci-Lab#	Description	UOM
200006776/ 05 001 059	AEB1141	Magnesium Perchlorate, Self-Indicating Granular (0.7-1.2mm)	100g
	AEB1255	Quartz Wool Discs (24mm)	25
200010160/ 38.00-0124	AEB1304	Brass Wool	50g
200008689/ 05 002 799	AEB1354	Aquatak (drying agent) without indicator	50g
200010245/ 50 008 467	AR01008	Corundum Balls	60g
200004827/ 03 679 908	AR177	Quartz Wool, Fine	50g



## Operational Accessories


Elementar#	Sci-Lab#	Description	UOM
200006785/ 05 000 094	AEE2505	Gloves, Temperature Resistant	Pair
200014862/ 34.00-0099/4	AEE2527	Powder Filling Funnel (large) w/Silicone Tubing Outlet	EA
200013169/ 05 001 715	AR01715	Cotton Wool	50g
200014862/ 03 968 006	AR241	Silicone Grease	35g

## Reference Card: *Elementar®* *sol*i TOC cube



## Quartz, Glassware, and Furnace Tubes

Elementar#	Sci-Lab#	Description	UOM
200015419/ 29.00-1078	AEC3067	Combustion Tube Quartz	EA



## O-ring

Elementar#	Sci-Lab#	Description	UOM
200014191/ 05 001 302	AEE1087	O-ring (7.59 x 2.62mm)	EA
200007904/ 05 000 568	AEE1175	O-ring (16 x 3mm)	EA
200007904/ 05 000 568	AEE1175-10	O-ring (16 x 3mm)	10
200008314/ 05 000 249	AR00249	O-ring (4.5 x 1.5mm)	EA
200008314/ 05 000 249	AR00249-10	O-ring (4.5 x 1.5mm)	10
200006004/ 05 000 416	AR00416	O-ring (7.5 x 2.5mm)	EA
200006004/ 05 000 416	AR00416-10	O-ring (7.5 x 2.5mm)	10
200008068/ 03 002 268	AR02268	O-ring (32 x 3mm)	EA
200010589/ 03 002 395	AR02395	O-ring (7 x 1.5 mm)	EA
200006143/ 03 002 607	AR02607	Shaft Seal	EA
200005999/ 05 000 353	AR50353	Square Gasket (7.65 x 1.78mm)	EA
200005999/ 05 000 353	AR50353-10	Square Gasket (7.65 x 1.78mm)	10
200014284/ 03 653 118	AR53118	O-ring (6 x 2mm)	EA